
Remoção do Cobre

Ferramenta	Tool Dia	Cut Z Min	Cut Z Max	Travel Z	Feedrate
Fresa de Gravação 60°	0.2	-0.04	-0.1	1	400
Fresa de Gravação 45°	0.18	-0.04	-0.1	1	400
Fresa de Gravação 30°	0.16	-0.04	-0.1	1	200
Fresa Multicorte 0,8	0.79	-0.04	-0.1	1	500
Fresa Multicorte 1,5	1.49	-0.04	-0.1	1	400
Fresa 2 Cortes 0,3	0.3	-0.02	-0.1	1	200
Fresa 2 Cortes 0,2	0.2	-0.02	-0.1	1	150

Recorte e Furos Fresados

Ferramenta	Tool Dia	Cut Z	Depth/Pass	Travel Z	Feedrate
Fresa Multicorte 0,8	0.79	-1.7	0.1	1	500
Fresa Multicorte 1,5	1.49	-1.7	0.1	1	400

Furos de Alinhamento

Ferramenta	Cut Z	Travel Z	Feedrate
Broca 1,0 mm	-3.9	1	400

Furação

Ferramenta	Cut Z	Travel Z	Feedrate
Broca 0,3 mm	-2	1	120
Broca 0,4 mm	-2	1	200
Broca 0,6 mm	-2	1	300
Broca 0,8 mm	-2	1	400
Broca 1,0 mm	-2	1	400
Broca 1,3 mm	-2	1	300
Broca 1,5 mm	-2	1	200
Broca 2,0 mm	-2	1	120
Broca 2,5 mm	-2	1	100
